



**ARCHICENTRE PRESENTS
A HOUSING STUDY OF SUBURBS OF NEW SOUTH WALES,
2007**



Suburbs Sorted by Rank for: Cracking

Suburb	Rank	Type of fault found - shown as a percentage of all houses inspected in each area								
		Damp	Framing	Illegal Building	Stump Faults	Timber Rot	Cracking	Electrical	Roofing	Water
Chatswood (41)	1	49%	29%	22%	24%	37%	61%	37%	46%	7%
Roseville (40)	2	43%	30%	20%	33%	30%	58%	35%	40%	3%
Willoughby (63)	3	56%	32%	24%	17%	33%	57%	41%	56%	8%
Newtown (66)	4	71%	41%	39%	30%	50%	53%	44%	48%	5%
Wahroonga (44)	5	48%	18%	32%	14%	50%	45%	27%	36%	14%
Surry Hills (44)	6	59%	14%	34%	5%	25%	43%	30%	32%	5%
Marrickville (52)	7	58%	17%	35%	21%	35%	40%	52%	50%	12%
Mosman (117)	8	48%	9%	25%	15%	22%	38%	15%	21%	3%
Lane Cove (58)	9	24%	14%	21%	21%	28%	31%	22%	29%	9%
Neutral Bay (50)	10	42%	14%	22%	20%	26%	30%	16%	26%	0%
Glebe (62)	11	48%	18%	18%	5%	21%	29%	29%	18%	2%
Leichhardt (66)	12	41%	26%	27%	14%	36%	27%	27%	29%	3%
Annandale (52)	13	46%	33%	25%	17%	35%	27%	21%	27%	2%
Balmain (126)	14	35%	16%	24%	14%	25%	20%	17%	22%	5%
Paddington (96)	15	54%	11%	26%	6%	28%	15%	18%	33%	2%
Rozelle (64)	16	34%	28%	20%	19%	38%	13%	19%	19%	2%
TOTALS(1,041)		47%	21%	26%	16%	31%	34%	26%	32%	5%